

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64

Version: Release 18.9.0

www.Ross-Tech.com

Dealer/Shop Name:

Workshop Code: 000 00000

Diagnostic Trouble Code Report

Thursday,25,January,2024,18:53:16:39370

VIN: WAUZZZ8PX5A029345 License Plate:

Mileage: Repair Order:

Control Module Part Number: 06F 906 056 CH HW: Hardware No

Component and/or Version: MED9.5.10 G00 6411

Software Coding: 0000075

Work Shop Code: WSC 01375 996 97137

VCID: 71E9EC346B30D0C22A-513C

4 Faults Found:

19490 - Intake Air Temperature Sensor 2 (G299)

P3034 - 002 - Signal too Large

17698 - Coolant Temp Sensor at Radiator Outlet (G83)

P1290 - 002 - Signal too Small

17700 - Map Controlled Engine Cooling Thermostat (F265)

P1292 - 004 - Open Circuit - MIL ON

16725 - Camshaft Position Sensor (G40)

P0341 - 004 - Implausible Signal

Readiness: 0110 0100