

Wednesday, 17, May, 2023, 18:20:02:52792

VCDS -- Windows Based VAG/VAS Emulator Running on Windows 11 x64

VCDS Version: 23.3.1.0 (x64) HEX-V2 CB: 0.4631.4

Data version: 20230421 DS346.2

www.Ross-Tech.com

VIN: WAUFFAFL1AN048737 License Plate: K690060

Mileage: 248720km-154547mi Repair Order:

Chassis Type: FL-AU48 (8T0)

Scan: 01 02 03 05 08 09 15 16 17 19 2E 42 46 47 52 53 55 56 62 72

77

VIN: WAUFFAFL1AN048737 Mileage: 248720km-154547miles

01-Engine -- Status: Malfunction 0010
02-Auto Trans -- Status: OK 0000
03-ABS Brakes -- Status: Malfunction 0010
04-Steering Angle -- Status: OK 0000
05-Acc/Start Auth. -- Status: OK 0000
08-Auto HVAC -- Status: Malfunction 0010
09-Cent. Elect. -- Status: OK 0000
15-Airbags -- Status: OK 0000
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
19-CAN Gateway -- Status: Malfunction 0010
2E-Media Player 3 -- Status: OK 0000
42-Door Elect, Driver -- Status: OK 0000
46-Central Conv. -- Status: Malfunction 0010
47-Sound System -- Status: OK 0000
52-Door Elect, Pass. -- Status: OK 0000
53-Parking Brake -- Status: Malfunction 0010
55-Headlight Range -- Status: OK 0000
56-Radio -- Status: Malfunction 0010
62-Door, Rear Left -- Status: OK 0000
72-Door, Rear Right -- Status: OK 0000
77-Telephone -- Status: OK 0000

Address 01: Engine (DL0MA-CAEB) Labels:| 06H-907-115-CAB.clb
Part No SW: 8K2 907 115 AL HW: 8K2 907 115 D
Component: 2.0l R4/4V TF H16 0001
Revision: E1H16--- CVN: CC36E0B0

Coding: 0104010A190F0160
Shop #: WSC 03805 002 1048576
ASAM Dataset: EV_ECM20TFS0118K2907115AL 001001
ROD: EV_ECM20TFS0118K2907115AL.rod
VCID: 79AFFE022955B142485-802C
VINID: 9D195659159C0517801081C31C663171BA

3 Faults Found:

4514 - Engine Speed Sensor (G28)

P0321 00 [096] - Implausible Signal

Intermittent - Not Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 2

Fault Frequency: 1

Mileage: 248712 km

Date: 2023.05.14

Time: 15:34:52

Engine RPM: 1287.00 /min

Normed load value: 11.4 %

Vehicle speed: 0 km/h

Coolant temperature: 82 °C

Intake air temperature: 41 °C

Ambient air pressure: 930 mbar

Voltage terminal 30: 12.133 V

Unlearning counter according OBD: 40

2837 - Fuel Rail/System Pressure

P0088 00 [237] - Too High

MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 2

Fault Frequency: 6

Mileage: 248713 km

Date: 2023.05.14

Time: 15:36:11

Engine RPM: 0.00 /min

Normed load value: 10.6 %

Vehicle speed: 22 km/h

Coolant temperature: 84 °C

Intake air temperature: 39 °C

Ambient air pressure: 930 mbar
Voltage terminal 30: 13.216 V
Unlearning counter according OBD: 40

4737 - Signal Line for Fuel Pump Electronics
P3089 00 [096] - Electrical Malfunction
Intermittent - Not Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001
Fault Priority: 2
Fault Frequency: 1
Mileage: 248720 km
Date: 2023.05.15
Time: 11:08:21

Engine RPM: 969.50 /min
Normed load value: 12.5 %
Vehicle speed: 0 km/h
Coolant temperature: 51 °C
Intake air temperature: 30 °C
Ambient air pressure: 930 mbar
Voltage terminal 30: 12.298 V
Unlearning counter according OBD: 40

Readiness: 0110 0101

Address 02: Auto Trans (J217) Labels:| 0B6-927-156.clb
Part No SW: 8K0 927 158 J HW: 0B6 927 156
Component: 0B6 20TFSIUSA H05 0008
Revision: --H05--- CVN: 1C1436D7
Coding: 001012
Shop #: WSC 02145 785 00200
ASAM Dataset: EV_TCMAL651 A01006
ROD: EV_TCMAL651.rod
VCID: 3D272A127DFD4D6224D-8068

No fault code found.

Address 03: ABS Brakes (J104) Labels:. 8K0-907-379-V1.clb
Part No SW: 8K0 907 379 CA HW: 8K0 907 379 CA
Component: ESP8 quattro H04 0010
Revision: ----- Serial number: -----

Coding: 150D18
Shop #: WSC 02391 823 56573
VCID: 7AADE10E2CD3BA5A41F-802E

3 Faults Found:

02214 - Tire Pressure Warning

000 - - - Intermittent

Freeze Frame:

Fault Status: 00100000

Fault Priority: 4

Fault Frequency: 2

Reset counter: 225

Mileage: 248060 km

Time Indication: 0

Date: 2023.03.14

Time: 12:20:52

Freeze Frame:

Hex Value: 0x5400

Hex Value: 0x4006

Hex Value: 0x1F37

Hex Value: 0x1EAC

Hex Value: 0x00FF

01314 - Engine Control Module

013 - Check DTC Memory - Intermittent

Freeze Frame:

Fault Status: 00101101

Fault Priority: 6

Fault Frequency: 11

Reset counter: 240

Mileage: 248698 km

Time Indication: 0

Date: 2023.03.27

Time: 09:49:59

Freeze Frame:

Hex Value: 0x0D00

Hex Value: 0x4002

Hex Value: 0x1226

Hex Value: 0x46A5

Hex Value: 0x00FF

00473 - Control Module for Elect. Park/Hand Brake (J540)

013 - Check DTC Memory - Intermittent

Freeze Frame:

Fault Status: 00101101
Fault Priority: 6
Fault Frequency: 1
Reset counter: 240
Mileage: 248698 km
Time Indication: 0
Date: 2023.03.27
Time: 09:50:00

Freeze Frame:

Hex Value: 0x0D00
Hex Value: 0x6202
Hex Value: 0x1232
Hex Value: 0x02A4
Hex Value: 0x00FF

Address 05: Acc/Start Auth. (J393) Labels: 8K0-907-064-05.clb
Part No SW: 8K0 907 064 DG HW: 8K0 907 064 DG
Component: BCM2 1.1 H02 0327
Revision: 00002001
Coding: 090100
Shop #: WSC 02399 823 56573
VCID: 78A9FB0612DFA84A37B-802C

Subsystem 1 - Part No SW: 8T0 959 754 A HW: 8T0 959 754 A
Component: FBSAUDIB8 IDG H37 0060
Serial number: 0510000003717014

Subsystem 2 - Part No SW: 8K0 905 852 D HW: 8K0 905 852 D
Component: J764 ELV MLB H37 0042
Serial number: 0210000001913009

No fault code found.

Address 08: Auto HVAC (J255) Labels: 8Tx-820-043-3Z.clb
Part No SW: 8T1 820 043 AQ HW: 8T1 820 043 AQ
Component: KLIMA 3 ZONEN H08 0171
Revision: C1000000 Serial number: 01220120101045
Coding: 64002000

Shop #: WSC 02391 823 56573
VCID: 005993E64A0FE08A0FB-8054

2 Faults Found:

00710 - Defroster Flap Positioning Motor (V107)

001 - Upper Limit Exceeded

Freeze Frame:

Fault Status: 01100001

Fault Priority: 3

Fault Frequency: 3

Reset counter: 199

Mileage: 246785 km

Time Indication: 0

Date: 2023.03.11

Time: 15:03:09

Freeze Frame:

Voltage: 12.00 V

Temperature: 14.0°C

Temperature: 6.0°C

Count: 11234

Count: 12338

Bin. Bits: 01000000

Bin. Bits: 10000011

Time: 9.00 s

01206 - Signal for Duration of Ignition Off Time

008 - Implausible Signal - Intermittent

Freeze Frame:

Fault Status: 00101000

Fault Priority: 7

Fault Frequency: 2

Reset counter: 242

Mileage: 248704 km

Time Indication: 0

Date: 2009.06.26

Time: 00:22:04

Address 09: Cent. Elect. (J519) Labels: 8K0-907-063.clb
Part No SW: 8K0 907 063 P HW: 8K0 907 063 P
Component: BCM1 1.0 H25 0380
Revision: 10025001 Serial number: 00000000447085

Coding: 26001091063CAF010000080300003D0D0F1C520800010161000000
Shop #: WSC 02391 823 56573
VCID: 3C2127166667446A133-8068

Subsystem 1 - Part No SW: 8K1 955 119 A HW: 8T1 955 119 Labels: 1KX-955-119.CLB
Component: WWS 180110 H06 0070
Serial number: SWF10010180294
Coding: 00FD11

Subsystem 2 - Part No SW: 8K0 955 559 HW: 8K0 955 559 Labels: 8K0-955-559.CLB
Component: RLS H04 0003
Serial number: 10753895
Coding: 025028

Subsystem 3 - Part No SW: 8K0 941 531 AL HW: 8K0 941 531 AL
Component: E1 - LDS H08 0090
Serial number: 00000000001801100926

Subsystem 4 - Part No SW: 8K0 907 410 B HW: 8K0 907 410 B
Component: HOMELINK H01 0010

No fault code found.

Address 15: Airbags (J234) Labels:| 8K0-959-655.clb
Part No SW: 8K0 959 655 H HW: 8K0 959 655 H
Component: AirbagVW-AU10 H39 0560
Serial number: 003EGD05FYM- Dataset Number: 8K0909602J0001
Coding: 303837354230303030304A55304C384B3053
Shop #: WSC 02145 785 00200
ASAM Dataset: EV_AirbaECUVWAUDI010 003010
ROD: EV_AirbaECUVWAUDI010_003_AU48.rod
VCID: 42DD59EE0403329A59F-8016

Seat occupied recognition:

Subsystem 1 - Part No SW: 8K0 959 339 B HW: 8K0 959 339 B
Component: BF-Gewichtss. H01 0030
Serial number: 5810000R0900005D4J

Crash sensor for side airbag: driver side:
Serial number: 6334MSME4F203376D

Front Passenger's Side Airbag Crash Sensor:
Serial number: 6344MSME4F526C02K

Rear Side Airbag Crash Sensor (on driver's side):
Serial number: 6352QSME424B21348

Passenger side rear thorax airbag crash sensor:
Serial number: 6362QSME694B2E18X

Crash sensor for front airbag: driver side:
Serial number: 63732SME564C5314\$

Crash sensor for front airbag: front passenger side:
Serial number: 63832SME4C4C17120

No fault code found.

Address 16: Steering wheel (J527) Labels: 8K0-953-568.clb
Part No SW: 8K0 953 568 F HW: 8K0 953 568 F
Component: Lenks.Modul H16 0014
Revision: ----- Serial number: 90315JAP000AU
Coding: 000016
Shop #: WSC 02391 823 56573
VCID: 3D272A127D7D4D6224D-8068

Component: E221 - MFL H02 0010

No fault code found.

Address 17: Instruments (J285) Labels: 8T0-920-xxx-17.clb
Part No SW: 8K0 920 950 E HW: 8K0 920 950 E
Component: KOMBIINSTR. H20 0255
Revision: 00100000 Serial number: CIM17RA1A
Coding: 8B1609000300D705020000
Shop #: WSC 02391 823 56573
VCID: 313F0622B125B902B05-8064

No fault code found.

Address 19: CAN Gateway (J533) Labels: 8T0-907-468.clb
Part No SW: 8T0 907 468 R HW: 8T0 907 468 H
Component: GW-BEM 5CAN H06 0105
Revision: GB600050 Serial number: 5000G10121821E

Coding: 00C303
Shop #: WSC 02391 823 56573
VCID: 50F963A6DAEFD00ADFB-8004

Subsystem 1 - Part No SW: 8K0 915 181 E HW: 8K0 915 181 E
Component: J367-BDM H07 0170
Serial number: 1000336C200110

1 Fault Found:

03041 - Energy Management Active

000 - - - Intermittent

Freeze Frame:

Fault Status: 00100000

Fault Priority: 7

Fault Frequency: 1

Reset counter: 240

Mileage: 248703 km

Time Indication: 0

Date: 2023.04.08

Time: 12:24:17

Freeze Frame:

Bin. Bits: 11111

Voltage: 10.50 V

Count: 6

Address 2E: Media Player 3 (R199) Labels: 8T0-035-785.clb
Part No SW: 8T0 035 785 A HW: 8T0 035 785
Component: SG ext.Player H08 0280
Revision: 00000000
Coding: 020302
Shop #: WSC 02391 823 56573
VCID: 392F3E0269557142085-806C

No fault code found.

Address 42: Door Elect, Driver (J386) Labels: 8K0-959-793.clb
Part No SW: 8K0 959 793 H HW: 8K0 959 793 D
Component: TSG FA H11 0306
Revision: Serial number: 0000009959582
Coding: 011C03204000410001

Shop #: WSC 02391 823 56573
VCID: 45D742F215AD05A27CD-8010

No fault code found.

Address 46: Central Conv. (J393) Labels: 8K0-907-064-46.clb
Part No SW: 8K0 907 064 DG HW: 8K0 907 064 DG
Component: BCM2 1.1 H02 0327
Revision: 00002001 Serial number: 0126397888
Coding: 0106023A007A440400B0013200000000
Shop #: WSC 02391 823 56573
VCID: 78A9FB0612DFA84A37B-802C

Subsystem 1 - Part No SW: 8K0 959 719 HW: 8K0 959 719
Component: GTO BF H06 0050
Serial number: 00000000000000214998

Subsystem 2 - Part No: 1K0 951 605 C
Component: LIN BACKUP HO H05 1501

Subsystem 3 - Part No SW: 8K0 959 591 A HW: 8K0 959 591
Component: J245 PS037 H06 0041

1 Fault Found:

01503 - Bulb for 3rd Brake Light (M25)
012 - Electrical Fault in Circuit - MIL ON
Freeze Frame:
Fault Status: 11101100
Fault Priority: 2
Fault Frequency: 1
Reset counter: 87
Mileage: 171107 km
Time Indication: 0
Date: 2019.05.23
Time: 09:33:39

Address 47: Sound System (J525) Labels: 8T0-035-223-ASC.clb
Part No SW: 8T0 035 223 AH HW: 8T0 035 223
Component: DSP STD H07 0230
Revision: S2200000
Coding: 0203010102

Shop #: WSC 02391 823 56573
VCID: 74B1CF360EB7CC2A1B3-8020

No fault code found.

Address 52: Door Elect, Pass. (J387) Labels: 8K0-959-792.clb
Part No SW: 8K0 959 792 H HW: 8K0 959 792 D
Component: TSG BF H11 0306
Revision: Serial number: 0000009972259
Coding: 011C03204000410001
Shop #: WSC 02391 823 56573
VCID: 44D15FF61E973CAA6B3-8010

No fault code found.

Address 53: Parking Brake (J540) Labels: 8K0-907-801-V1.clb
Part No SW: 8K0 907 801 H HW: 8K0 907 801 H
Component: EPB Audi B8 H09 0100
Revision: 00000003 Serial number: 10000000423554
Shop #: WSC 00000 000 00000
VCID: 34310F364E378C2ADB3-8060

1 Fault Found:

01314 - Engine Control Module

013 - Check DTC Memory - Intermittent

Freeze Frame:

Fault Status: 00101101

Fault Priority: 4

Fault Frequency: 11

Reset counter: 240

Mileage: 248698 km

Time Indication: 0

Date: 2023.03.27

Time: 09:50:00

Freeze Frame:

Voltage: 13.20 V

Count: 58

Speed: 14.0 km/h

Hex Value: 0x0260

Hex Value: 0x0004

Hex Value: 0x0101

Address 55: Headlight Range Labels: 8K0-907-357.clb
Part No: 8K5 907 357
Component: Dynamische LWR H01 0010
Revision: 00000001 Serial number:
Coding: 0000004
Shop #: WSC 02145 785 00200
VCID: 77ABF83A13C1A7323E1-8022

No fault code found.

Address 56: Radio (J503) Labels: 8Tx-035-1xx-56.clb
Part No SW: 8T1 035 186 R HW: 8T1 035 186 R
Component: Con3 Sirius H06 0351
Revision: 00000008 Serial number: AUZ5Z6J1341547
Coding: 04020002010185004359070800
Shop #: WSC 02391 823 56573
VCID: 46D545FE28AB0EBA757-8012

Subsystem 1 - Part No SW: 8T0 919 603 E HW: 8T0 919 603 E
Component: Display

1 Fault Found:

02635 - Tuner Not Enabled/Activated

000 - -

Freeze Frame:

Fault Status: 01100000

Fault Priority: 7

Fault Frequency: 1

Reset counter: 220

Mileage: 199291 km

Time Indication: 0

Date: 2021.02.01

Time: 14:49:03

Address 62: Door, Rear Left (J388) Labels: 8K0-959-795.clb
Part No SW: 8K0 959 795 C HW: 8K0 959 795 C
Component: TSG HL H10 0306
Revision: Serial number: 0000102747014

Coding: 010C03204000210001
Shop #: WSC 02391 823 56573
VCID: 42DD59EE0483329A59F-8016

No fault code found.

Address 72: Door, Rear Right (J389) Labels: 8K0-959-795.clb
Part No SW: 8K0 959 795 C HW: 8K0 959 795 C
Component: TSG HR H10 0306
Revision: Serial number: 0000102746875
Coding: 010C03204000210001
Shop #: WSC 02391 823 56573
VCID: 42DD59EE0483329A59F-8016

No fault code found.

Address 77: Telephone Labels: 8P0-862-335.lbl
Part No SW: 8T0 862 336 D HW: 8T0 862 336 D
Component: FSE_256x BT H39 0600
Revision: 00000000 Serial number: 00000005067746
Coding: 0010370
Shop #: WSC 02335 785 00200
VCID: 3C2127166A67446A133-8068

No fault code found.

End----(Elapsed Time: 01:47, VBatt start/end: 12.0V/11.9V. VIgn 12.0V)-----