

# KDIAG Diagnostic report:

Diagnosis name:Audi

Diagnostic items:Health Report

Diagnosis time:2026-02-26

10:23:23

## Diagnostic content:

### (1)01 Engine-Fault

1,TPCAN01: 24001648

2,TPCAN01: 24001626

3,TPCAN01: 24001626

### (2)02 Auto Trans-Fault

1,TPCAN01: P1881 Target  
Acceleration Signal missing  
Message

2,TPCAN01: P1854 Databus  
Drivetrain faulty

3,TPCAN01: P1852 Databus  
Drivetrain implausible Message  
From Engine CM

### (3)03 ABS Brakes-Fault

1,TPCAN01: 01315

Transmission Control Module  
(TCM)

2,TPCAN01: 01312 Drive Train  
Data Bus

3,TPCAN01: 01826 Steering  
Angle Sensor, Voltage Supply  
Terminal 30

### (4)09 Cent. Elect.-Fault

1,BOSCH: 01494 Left Side  
Marker Lamp Bulb

2,BOSCH: 01498 Right Side  
Marker Lamp Bulb

(5)17 Instruments-Fault

1,KWP01: 01315 Transmission  
Control Module (TCM)

2,KWP01: 01312 Drive Train Data  
Bus

(6)25 Immobilizer-Fault

1,KWP01: 01315 Transmission  
Control Module (TCM)

2,KWP01: 01312 Drive Train Data  
Bus

(7)55 Xenon Range-Fault

1,TPCAN01: 01312 Drive Train  
Data Bus

2,TPCAN01: 01317 Instrument  
Cluster Control Module

(8)15 Airbags-Fault

1,TPCAN01: 01316 Brake Control  
Module

(9)46 Central Conv.-Fault

1,BOSCH: 00957 Key 3

(10)16 Steering Wheel-Normal